



BRICK LANE

CASE STUDY · JUNE 2026

INSIDE THIS CASE STUDY

Contents

A full record of the renovation we carried out at this property, from the works completed across the flat to the before and after photography of each stage.

03 **Renovation Overview** ›
Water-damage treatment and full redecoration across the flat.

04 **Before Works** ›
The flat as we found it: extensive water damage, perished plaster and lifting lining paper.

10 **After Works** ›
The finished flat: walls made good, sealed and redecorated throughout in grey.

Tap any entry above to jump straight to that section.





What we did

SECTION 1

Treating Water Damage

Treated extensive water damage across various walls in the flat:

- Wall surfaces restored by removing the damaged materials and replacing them
- Lining paper replaced where necessary
- Walls prepared for painting

Prepared walls and woodwork:

- Sanded, primed and sealed the wall surfaces, alongside other minor repairs

SECTION 2

Decorating

Painted all walls in grey.

Photographs of each stage follow, grouped into **Before Works** and **After Works**, with before and after comparisons side by side. Use the contents page to jump straight to any stage.





STAGE ONE

Before Works













STAGE TWO

After Works









ALL IN HOUSE PROPERTY GROUP

NEVER PAY MORE FOR LESS AGAIN



020 3488 8072
Call us



Email us:
info@aihpg.com