



CITY HEIGHTS

CASE STUDY · JUNE 2026

INSIDE THIS CASE STUDY

Contents

A full record of the renovation we carried out at this property, from the works completed across every room to the before, during and after photography of each stage.

-
- 03** **Renovation Overview** >
- Every room and task completed across the flat, restoration and decoration throughout.
-
- 04** **Before Works** >
- The flat as we found it: marked walls, damp spotting, cracks and damaged plaster.
-
- 07** **During Works** >
- Works in progress: walls prepared and made good, then redecorated room by room.
-
- 09** **After Works** >
- The finished flat: clean, freshly painted walls and ceilings throughout.
-

Tap any entry above to jump straight to that section.





What we did

SECTION 1

Bathroom

Wall and ceiling restoration

Repaired and filled damages and imperfections on the walls and ceiling.

Painting

Applied one coat of paint to the ceiling.

SECTION 2

Reception / Kitchen Area

Wall restoration

Repaired and filled damages and imperfections on the walls.

Painting

Applied one coat of paint to the walls.

SECTION 3

Kitchen

Painting

Applied one coat of paint to the walls and ceiling.

SECTION 4

Hallway

Wall and ceiling restoration

Repaired and filled damages and imperfections on the walls and ceiling.

Painting

Applied one coat of paint to both the walls and ceiling.

SECTION 5

Complimentary Services

After-works cleaning


A comprehensive clean of the property on completion of all renovation works.

Photographs of each stage follow, grouped into **Before Works**, **During Works** and **After Works**. Use the contents page to jump straight to any stage.



STAGE ONE

Before Works








STAGE TWO

During Works






STAGE THREE

After Works







ALL IN HOUSE PROPERTY GROUP

NEVER PAY MORE FOR LESS AGAIN



020 3488 8072
Call us



Email us:
info@aihpg.com