



VILLERS

CASE STUDY · 01/06/2026

INSIDE THIS CASE STUDY

Contents

A full record of the renovation we carried out at this property, from the works completed across every room to the before, during and after photography of each stage.

-
- | | | |
|---|----------------------------|---|
| 03 | Renovation Overview | > |
| Every trade and task completed across the flat, room by room. | | |
-
- | | | |
|---|---------------------|---|
| 05 | Before Works | > |
| The flat as we found it: dated fittings, marked walls and worn carpets. | | |
-
- | | | |
|--|---------------------|---|
| 21 | During Works | > |
| Works in progress: rewiring, new fittings and full redecoration. | | |
-
- | | | |
|--|--------------------|---|
| 29 | After Works | > |
| The finished flat: herringbone floors, refreshed kitchen and bathroom, modern electrics. | | |
-

Tap any entry above to jump straight to that section.





What we did

SECTION 1

Decorating

Painted all walls and ceilings throughout in white.

Painted all woodwork, including:

- Skirting boards (replaced)

- Five doors and doorframes (new door-lock mortices added)

- Five internal window frames

- Wardrobes where fitted

Repaired walls and woodwork:

- Filled holes and other minor repairs

SECTION 2

Bathroom

RegROUTED and re-siliconed as needed.

SECTION 3

Kitchen

Partial regROUTING and re-siliconing.

Removed and disposed of the old gas hob and installed a new one.

Removed and disposed of the old kitchen sink and tap and installed new ones, including removal of the waste-disposal unit and the associated pipe rework.

SECTION 4

Additional Works

Installed movable shelving in the storage cupboard.

Tidied the cables for the existing TV.

Replaced five door handles with new door-lock mortices.



What we did (continued)

SECTION 5

Electrics

Replaced

- Six light switches (from single dimmers)
- Ten double power sockets (now USB-enabled)
- One bathroom fan
- Seven ceiling lights
- The wall-mounted thermostat, with a more modern unit

Removed

- One burglar-alarm panel
- The battery pack and sensors
- Four room sensors

SECTION 6

Gas Works

Boiler service completed and the landlord gas safety certificate obtained.

SECTION 7

Flooring

Removed the existing flooring.

Installed

- Laminate flooring (floor provision not included)
- Carpet, underlay and entrance trims in the specified colour

Photographs of each stage follow, grouped into **Before Works**, **During Works** and **After Works**. Use the contents page to jump straight to any stage.

STAGE ONE

Before Works



To be removed













Carpet choice

CarpetWarehouse

Ariel Silver

We're proud of our hand selected range of high quality carpet at the UK's best prices. For an instant quote or to book a measure via video call, visit www.carpetwarehouse.co.uk today.

Pile Type	Saxony
Pile Height	14mm
Weight	2310g/m ²
Material	100% Polypropylene
Backing	Action

Features

-  Bleach Cleanable
-  Ideal for HEAVY Use
-  Stain Resistant

Room Suitability

-  Bedroom
-  Living Room
-  Stairs
-  Hallway
-  Dining Room

Call us on 0330 175 5667

Shading and colours may vary slightly between carpet rolls and samples.




















STAGE TWO

During Works
















A photograph of a hallway with two white doors. The door on the left is partially open, revealing a bathroom with a white sink and wooden cabinets. The door on the right is closed. The floor is covered in a patterned carpet. The image is dimly lit and has a dark overlay.

STAGE THREE

After Works








































ALL IN HOUSE PROPERTY GROUP

NEVER PAY MORE FOR LESS AGAIN



020 3488 8072
Call us



Email us:
info@aihpg.com